

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Ave. Torrance, CA 90502			A.State Manifest Document Number 84827656			
4. Generator's Phone (533-6677)			B.State Generator's ID			
5. Transporter 1 Company Name J. C. Liquid Waste Disposal			6. US EPA ID Number C A D 0 5 8 0 1 8 3 6	C.State Transporter's ID 64163		
7. Transporter 2 Company Name			8. US EPA ID Number	D.Transporter's Phone 213 268-3137		
9. Designated Facility Name and Site Address CASMALIA P.O. Box E NTU Road Casmalia, Ca 93429			10. US EPA ID Number C A D 0 2 2 0 7 4 8 1 2 5	E.State Transporter's ID		
				F.Transporter's Phone		
				G.State Facility's ID C A D 0 2 2 0 7 4 8 1 2 5		
				H.Facility's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12.Containers No.	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.
a. Waste alkaline liquid NOS Corrosive - NA1719			001	TT	-5000	G 123
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above			K.Handling Codes for Wastes Listed Above			
Solid * 9.0% Magnesium Hydroxide 2.0%			08/E(alt)			
Water 91.0% Silicon Oxide 2.0%						
*Chromic Hydroxide 25.0% Calcium Hydroxide 7.0%						
Aluminum Hydroxide 5.0%						
15. Special Handling Instructions and Additional Information Guide #60 Use gloves goggles respirator - May cause severe burns to skin & eyes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature sb	Date 06/17/86		
17. Transporter 1 Acknowledgement of Receipt of Materials			Date			
Printed/Typed Name C.B. Herbert - 57948			Signature C.B. Herbert	Month Day Year 06/17/86		
18. Transporter 2 Acknowledgement of Receipt of Materials			Date			
Printed/Typed Name Lillian Spence			Signature Lillian Spence	Month Day Year 06/18/86		
19. Discrepancy Indication Space SCANNED						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name Casmalia Resources			Signature Alice Christ	Date 06/18/86		

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Ave. Torrance, CA 90502			A.State Manifest Document Number 84827656		B.State Generator's ID	
4. Generator's Phone () 533-6677			C.State Transporter's ID 64163		D.Transporter's Phone 213-268-3137	
5. Transporter 1 Company Name J. C. Liquid Waste Disposal			6. US EPA ID Number C A D 0 5 8 0 1 8 3 6		E.State Transporter's ID	
7. Transporter 2 Company Name			8. US EPA ID Number		F.Transporter's Phone	
9. Designated Facility Name and Site Address CASMALIA P.O. Box E NTU Road Casmalia, Ca 93429			10. US EPA ID Number C A D 0 2 2 0 7 4 8 1 2 5		G.State Facility's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12.Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste alkaline liquid NOS Corrosive - NA1719			001	TT	-5000	G
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above			K.Handling Codes for Wastes Listed Above			
Solid * 9.0% Magnesium Hydroxide 2.0%						
Water 91.0% Silicon Oxide 2.0%						
*Chromic Hydroxide 25.0% Calcium Hydroxide 7.0%						
Aluminum Hydroxide 5.0%						
15. Special Handling Instructions and Additional Information Guide #60 Use gloves goggles respirator - May cause severe burns to skin & eyes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature <i>[Signature]</i>		Date 06/17/86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>[Signature]</i>		Date 06/17/86	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature <i>[Signature]</i>		Date 06/17/86	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name			Signature		Date Month Day Year	